









A=20  8,0 x 30mm	B=06  	C=20  3,5 x 30mm	D=06  4,0 x 25mm	E=04  3,0 x 16mm	F=08  6,0 x 10mm
G=04  M4,0 x 10mm	H=06  	I=14  	J=02  	K=04  214mm	

1




F x 4




6,0 x 10mm

K x 2



2




F x 4




6,0 x 10mm


K x 2



3



A x 4




8,0 x 30mm

C x 2



3,5 x 30mm

4



A x 4




8,0 x 30mm

C x 2




3,5 x 30mm


5



B x 6



6



A x 4




8,0 x 30mm

H x 6



7




D x 4



4,0 x 25mm

8






D x 2




4,0 x 25mm

9







1 x 14



10

2x



A x 8



8,0 x 30mm

E x 4



3,0 x 16mm

C x 16





3,5 x 30mm


J x 2



11



G x 4



M4,0 x 10mm



20.11.24 - Rev. 1